



R E L E A S E N O T E S

# 3-Series Firmware

1.600.0092 – May 11, 2019

## Product or Content Description

---

Package Update File for the CP3N

Package contents:

Cntrl Eng: v1.600.3781.33119

Updater: v 1.0.33

Bootloader: v1.29.00

RouterBootVersion: v4

RouterVersion: 1.004.0003

RouterRev2BootVersion: v205

RouterRev2Version: v 2.000.0053

IOPVersion: v1.3177.00007

## System Requirements and Dependencies

---

Software Requirements:

!! Device Database 91.00 or greater

## Operational Installation/Upgrade Instructions

---

When upgrading from 1.007.0019 or later, the recommended upgrade steps are:

- Use FTP client such as Filezilla to upload the file to \FIRMWARE, or using Toolbox FileManager, upload the file to \ROMDISK\USER\SYSTEM
- Using Text Console, use the command: PUF <Filename>

## Version History

---

Version 1.600.0092                      May 11, 2019

### Changes since Last Version

New features

- Upgraded cryptography libraries, used for TLS and SSH

## Updates

- General security enhancements
- General and stability enhancements for XiO Cloud
- General and stability enhancement for SNMP
- Enhancement for Certificate utilities
- Enhancements for AuditLog
- Enhancements for AutoUpdate
- Stability enhancements for RemoteSyslog
- Stability enhancements for Secure Sockets
- Stability enhancements for FITC connections
- Stability enhancements for Crestron Web Sockets
- Stability enhancements for BACNet
- Stability enhancements for 802.1x
- Remove unnecessary messages from logs

## Bugs

- Fix issue where closing instance of UDP socket in S+ code results in other instance not able to receive data
- Fix for MPC3-10x wakeup issue

## Known Issues

- SSLVERIFY is OFF in CA mode, it should be enabled
- When you are upgrading a router-based control system from 1.504 or before, if 802.1x was enabled, it will be disabled after the upgrade to 1.600. Please be aware that this means you may lose network connectivity, as the system won't authenticate on 802.1x.

## Version 1.504.0040.0004

February 14, 2019

### New features

- Added support for loading programs via XiO Cloud

### Updates

- XiO Cloud enhancements
- Update webserver to use TLS1.2
- Improve Secure Socket robustness

### Bugs

- Fix issues with LEDs in MPC3

## Version 1.503.0070.0001

November 16, 2018

### New features

- CTP and Telnet are disabled by default
- Add a default SSH Banner which prints a warning recommending securing the device

## Updates

- Updated support for XiO Cloud
- Updated support for Dynamic BACNet
- Updated support for BACNet stack
- Updated support for Auto Update
- Updated support for SNMP walks
- Stability update for Secure Client connections
- Stability update for Web Sockets
- Stability update for TimerEngine

### Version 1.503.0026

June 1, 2018

#### New features

- Updated IR support file with latest set of standard commands for Crestron Studio
- Support for new EISC's for communicating with Virtual Control

#### Bug fixes

- Resolved issue with data not being sent to extenders of GWEXER on update request
- Resolved issue with XiO Cloud connectivity

### Version 1.503.0016

February 28, 2018

#### New features

- Add support for XiO Cloud

#### Bug fixes

- Resolved router port forwarding issues at system boot
- Resolved BACNet COV issue

### Version 1.502.0039

August 15, 2017

#### Bug Fixes

- Resolve issues with exceptions when a 3 series is slaved to another 3 series controller
- Updated the range of valid ports allowed for BACnet

#### Known issues

- **When a system is configured with one of the time zones listed below, performing this firmware upgrade will set the time zone back to the default time zone of Pacific Standard Time**

Time Zone: 120 UTC-11

Time Zone: 121 Venezuela Standard Time

Time Zone: 122 Russia TZ 9 Standard Time

Time Zone: 123 W. Australia Standard Time

Time Zone: 124 W. Central Africa Standard Time

Time Zone: 125 W. Europe Standard Time

Time Zone: 126 W. Mongolia Standard Time

Time Zone: 127 West Asia Standard Time

Time Zone: 128 West Bank Gaza Standard Time

Time Zone: 129 West Pacific Standard Time

Time Zone: 130 Russia TZ 8 Standard Time

**The time zone should be set back to its correct configuration after upgrading the firmware**

- When Telnet and standard Web services are disabled and a firmware upgrade is performed the services will be re-enabled. After upgrading it will be necessary to disable them

Version 1.502.0029                      June 7, 2017

Updates

- Resolve issues with the rf subsystem being out of sync causing a loss in functionality unless the unit was rebooted.
- Resolve issues with the AutoUpdate engine.
- Resolve issues with the Bacnet Stack for Invoke Id optimizations
- Resolve issues with the printing of the username in the whoami command

Version 1.502.0026                      May 17, 2017

Updates

- Initial release for the ZUM-FLOOR-HUB

Version 1.502.0020                      April 6, 2017

Updates

- Add support for the IGMPProxy command.
- Resolve issues with Websockets connectivity.

Version 1.501.0106                      January 31, 2017

Updates

- Reduced extraneous messages in log.

Version 1.501.0008                      December 15, 2016

Updates

- Initial release for the DMPS3-4K-200-C / DMPS3-4K-300-C.

Version 1.501.0105                      November 7, 2016

Updates

- Reduced extraneous messages in log for websocket connections.

Version 1.501.0104                      October 26, 2016

Updates

- Improve network resilience for websocket connections
- Resolve issue with BACnet where network outage could cause devices to go offline

Version 1.501.0041                      October 14, 2016

Updates

- Resolved AV Framework and Fusion interoperability issues

Version 1.501.0103

October 4, 2016

#### Updates

- SIMPL Debugger fix
- Resolved issue where gratuitous ARPs would cause devices to lose IP address assignments.
- Added support for SHA256 Certificates.
- Added support for Crestron Web Scripting, allowing SIMPL# to tie into the built-in webserver.
- Optional parameters added to the CreateCSR command.
- Auto Update changes needed for the new tool.
- Resolved issues with TSW Panels not connecting over SSL.
- Resolved issues with 802.1X where we incorrectly advertised support for PEAPv1.
- BACnet fixes:
  - Foreign Device registration is now saved across reboots.
  - Added new console command to disable a Read following a write.
  - Memory leak fixes when NumberOfStates join was not being used for the Multi state.
  - Initiate Foreign device registration before sending out a WHO-IS or I-AM.
  - Resolve memory corruption issues.
  - Handle broadcast unconfirmed COV notifications.

## Licensing and Copyright Information

---

Certain Crestron products contain open source software. For specific information, please visit

[www.crestron.com/opensource](http://www.crestron.com/opensource)