

Crestron RL Release Notes

Crestron RL Version History

- Version 15.11.00
 - Version 15.10.00
 - Version 15.09
 - Version 15.08
 - Version 15.05
 - Version 15.04
 - Version 15.03
 - Version 15.02
-

Version 15.11.00

UC-CODEC

- LRS Software Version: **15.11.00**
 - Fixes an issue in which calling a phone number using the dialpad resolves to a Lync contact if the phone number is in the address book.
 - Fixes an issue in which the front of room display screen shows "loading" even after a participant starts desktop sharing into meeting.
 - Turns off the On-Screen Keyboard clicks by default
 - Replaces the text "Find someone using the search box", with "Find someone or dial a number" on the invite participant screen.
 - Adds the functionality to use LRS without having to change any settings/names or domains for an admin with different exchange(smtp) and Lync (sip uri) domain names.
 - Baseline image to improve the update process
 - Improved error messaging when checking updates
- Crestron Firmware version: **1.00.11.066**
 - Fixed issue that caused language bar to not show up on Administrator login page
 - Fixed unlimited size of service.log file. 3 Mb max.
 - Added relative controls for PTZ camera (left, right, up, down buttons)
 - Camera presets default to standard zoom levels instead of all preset to default location
 - Removed obsolete Lync and LRS versions from Installed Packages list on Crestron System page
 - WinSAT scores are added to the device with this update
 - Fixed an issue that caused the TS-1051 display to time out and go to sleep before the other displays after a reboot

- Default network authentication profile will not set the 'Enforce' option now
- Added the ability to import and clear custom network authentication profile files on the Security page
- Added zoom in and out buttons to the Camera page of the default Crestron project
- Added control to Advanced settings page to enable "Intel AMT Mode" for remote system management

CCS-TX-201

Firmware Version: **1.1855.00007**

- No Changes

CCS-TS-1051

Firmware Version: **1.1855.00007**

Bootloader Version: **1.0000.186**

- No Changes

Version 15.10.00

UC-CODEC

- LRS Software Version: **15.10.00**
 - Microsoft Documentation:
 - [KB2962967](#) - Release Documentation
 - [KB2972296](#) - Lync Room System is stuck to a "joining conference room to meeting" message when you join a Lync meeting
 - [KB2933446](#) - If you run System Center Operations Manager 2012, join Lync Room System to the domain before you install the June 2014 or April 2014 update
 - Adds functionality to improve the content capture experience for a computer that is always connected in the Lync Room System.
 - Fixes an issue in which Lync Room System does not display recurring meetings until Lync Room System restarts.
 - Fixes an issue to increase the zone of action of the tabs on the console.
 - Fixes an issue that in which later searches do not start at the top of the results set when you invite participants.
 - Fixes several issues that occur in large meeting and the default display views.
 - Fixes an issue in which the positions of the language bar moves after you change languages.
 - Fixes an issue in which you cannot start a whiteboard when I'm a Whiteboard was selected from the front of Lync Room System screens.

- Adds functionality that enables Lync Room System administrative web portal to support different user principal name (UPN) and Session Initiation Protocol (SIP).
- Fixes an issue in which you cannot join a meeting on the Lync Room System side. However, Lync Room System shows that you have joined as a remote participant.
- **Crestron Firmware version: 1.00.10.084**
 - USB Camera page added with camera preview and digital PTZ settings. 4 Presets are available.
 - LRS software version added to Crestron console "ver all" command.
 - Fixed issue that caused the list of keyboards on the language bar to keep growing after Chinese is added.
 - All UI text translated to all available languages.
 - Added options to Advanced settings page to clear Lync User cache and flush local DNS cache.
 - Fixed issue that caused language bar to fail to show up in Administrator mode
 - Added control to disable LRS restart when displays are plugged in or unplugged
 - Added console command to enable High Security mode for government deployments
 - Moved Proxy Server control UI to a new dedicated page
 - Added support for Proxy Server automatic configuration scripts
 - Fixed display change logging errors
 - UI changes to allow for disabled buttons, toggles, and sliders
 - Added support to Crestron Updater (COU) for proxy server username and password to be passed as parameters
 - Added controls to enable 802.1X network authentication to Security page
 - Added a window to show the JITC banner message before starting LRS in admin, High Security mode.
 - Updated LRS version number detection to match LRS 15.10 bits
 - Added camera preset page to built-in Splash project
 - Added check for PPI displays at high frequencies. Fix the frequency on startup if needed.
 - Added continue option to DNS cache clear button and updated option on Lync cache clear button.

CCS-TX-201

Firmware Version: **1.1855.00007**

- No Changes

CCS-TS-1051

Firmware Version: **1.1855.00007**

Bootloader Version: **1.0000.186**

- No Changes

Version 15.09

UC-CODEC

- LRS Software Version: **15.09**
 - Fixed issue during 15.08 update that locked system when processing update 7 of 7.
- Crestron Firmware version: **1.00.06.009**
 - No Changes

CCS-TX-201

Firmware Version: **1.1855.00007**

- No Changes

CCS-TS-1051

Firmware Version: **1.1855.00007**

Bootloader Version: **1.0000.186**

- No Changes
-

Version 15.08

UC-CODEC

- LRS Software Version: **15.08**
 - Added support for the admin to specify multiple user input languages, and for the users to switch between admin-defined input languages and IMEs.
 - Fixed an issue that would prevent users from inviting other users by phone number into a meeting, when those participants are not in the directory.
 - Added SCOM pack agent
 - Various fixes to narrator and high contrast support
 - Fixed an issue preventing new or updated recurring meetings from being reflected on the room calendar until the device is restarted.
 - Lync licensing and activation support
 - Performance improvements in joining large meetings.
 - SCOM clearing events
 - Added additional download retry logic in the device's update service to better handle transient connection issues.

- Added informative illustrations to the on-screen device tutorial.
 - Fixed several bugs that could cause UI animations to render incorrectly.
 - Fixed the behavior of popup menus in various places.
 - Fixed an issue preventing the device to join online meetings scheduled via OWA.
 - Improved the user experience when an incoming call or meeting invite notification is presented while the on-screen keyboard is in use.
 - Fixed an issue that could result in some search result items to be duplicated
 - Fixed an issue that could prevent the meeting countdown from appearing, or could cause it to display an incorrect value.
 - Fixed whiteboard first touch issue.
- Crestron Firmware version: **1.00.06.009**
 - Language features added for keyboard, locale, and location
 - UI changes to properly set translated text to window captions of all controls for Narrator.
 - Changes for MS CU5 update. Added SCOM button, removed update buttons, changed Update page to Smart Graphics page, removed License page, and set tab orders and focus changes for narrator.
 - Changes to allow Crestron UI to respond to system themes.
 - Changed LyncRoomTracing log directory in log export.
 - COU.exe now supports command line parameter for specific update manifest.

CCS-TX-201

Firmware Version: **1.1855.00007**

- No Changes

CCS-TS-1051

Firmware Version: **1.1855.00007**

Bootloader Version: **1.0000.186**

- No Changes

Version 15.05

UC-CODEC

- LRS Software Version: **15.05**
 - Fix for LyncRoom user password corruption issue: [KB2920614](#)
 - Fix for Lync presence user interface element not displaying after reboot: [KB2921197](#)
- Crestron Firmware version: **1.00.01.972**

- Added new "Advanced" settings page with USB reset button and adv. Display settings.
 - Moved online update button to Advanced page as Support System Update
 - Feature added where Crestron Audio Setup user can select a usb audio input device from a list of attached input devices
 - Added options to import and view Intermediate CA's in interface.
 - Apply static IP settings when cable is not connected or when DHCP server is not present.
 - Changed Network setup page to use toggle switches for DHCP modes.
- Connectivity Analyzer pack included

CCS-TX-201

Firmware Version: **1.1855.00007**

- No Changes

CCS-TS-1051

Firmware Version: **1.1855.00007**

Bootloader Version: **1.0000.186**

- No Changes
-

Version 15.04

UC-CODEC

- LRS Software Version: **15.04**
 - No Changes
- Crestron Firmware version: **1.00.01.971**
 - Fix to root certificate name rendering in OEM Settings / Security page cert list
 - Added feature to list and set screen resolutions and timings of front displays in Test settings page
- Content Input update pack included
- Root Cert update pack included

CCS-TX-201

Firmware Version: **1.1855.00007**

- No Changes

CCS-TS-1051

Firmware Version: **1.1855.00007**

Bootloader Version: **1.0000.186**

- No Changes
-

Version 15.03

UC-CODEC

- LRS Software Version: **15.03**
 - Microsoft CU3 update release
 - Accessibility updates
 - VMR access through Dial Pad
 - LRS Admin Portal support added
- Crestron Firmware version: **1.00.01.970**
 - No Changes

CCS-TX-201

Firmware Version: **1.1855.00007**

- No Changes

CCS-TS-1051

Firmware Version: **1.1855.00007**

Bootloader Version: **1.0000.186**

- No Changes
-

Version 15.02

UC-CODEC

- LRS Software Version: **15.02**

- Initial Release
- Crestron Firmware version: **1.00.01.970**
 - Initial Release

CCS-TX-201

Firmware Version: **1.1855.00007**

- Initial Release

CCS-TS-1051

Firmware Version: **1.1855.00007**

Bootloader Version: **1.0000.186**

- Initial Release
-