



RELEASE NOTES

UC-SB1

(UC-SB1, UC-SB1-CAM, UC-SB1-CAM-FLEX)

2.004.001.020

Product or Content Description

This firmware applies to all Crestron UC-SB1 models.

Please see the soundbar product pages on the Crestron website for release notes and downloads.

System Requirements and Dependencies

Required minimum software versions:

Crestron Toolbox Version: 3.03.133 or later

Operational Installation/Upgrade Instructions

The firmware will be upgraded through Toolbox, please visit the following online help article for further details.

[Crestron Flex Soundbar Insider](#)

Version History

Version 2.004.001.020

September 2022

Device Features Include:

- USB library update.
- Soundbar firmware version for enhanced audio properties.

Version 2.003.098.056

March 2022

Device Features Include:

- USB library update.
- Soundbar firmware version for certified audio properties.

Version 2.001.098.030

June 2021

Device Features Include:

- Support for the latest DSP chip.

Device Behaviors:

- No backwards compatibility from 2.001.xxx.xxx firmware to 1.002.xxx.xxx.

Version 1.002.001.011

November 2019

Device Features Include:

- Increased maximum output volume.
- Slightly increased bass.

Version 1.001.098.026

November 2019

Device Features Include:

- Increased default speaker output volume
- Combined firmware for all UC-SB1* models

Known Issues:

- If upgrading from a previous version and running in a Microsoft Teams Room Flex System, the Soundbar may need to be re-selected as the default audio device for the system after the upgrade.

Version 1.001.096.024

May 2019

Device Features Include:

- Improved soundbar audio

Known Issues:

- If upgrading from a previous version and running in a Microsoft Teams Room Flex System, the Soundbar may need to be re-selected as the default audio device for the system after the upgrade.

Version 1.001.092.008

April 2019

Device Features Include:

- Camera upgrade supported via UC-ENGINE

Known Issues:

- If upgrading from a previous version and running in a Microsoft Teams Room Flex System, the Soundbar may need to be re-selected as the default audio device for the system after the upgrade.

Version 1.001.0086

February 2019

Device Features Include:

- Initial Firmware Release for UC-SB1-FLEX & UC-SB1-CAM-FLEX.

Known Issues:

- Camera firmware updating is not supported in Crestron Toolbox for the UC-SB1-CAM.

Licensing and Copyright Information

Certain Crestron products contain open-source software. For specific information, please visit www.crestron.com/opensource